







VISION GEN.4 CONNECTORS | A4/X4 / G4/P4

1. MONTAGE UND INSTALLATION | MOUNTING AND INSTALLATION:



IMPORTANT:

- all sections must be perfectly in line and if surface isn't even make sure the elements are horizontally mounted
- if these conditions are not satisfied gaps will be the result

