



1. MONTAGE UND INSTALLATION | MOUNTING AND INSTALLATION:




Remove the LED inset to get access to branch circuit.


1. Bei allen Montagearbeiten Handschuhe tragen.
Use gloves when handling the fixture.



2. Installation openings according to the technical drawing.




3.



Stecker für die elektrische
Verbindung der Lichteinsätze

Plug for electrical connection
of lighting insets

4.




Dichtung zur Beseitigung von
seitlichen Lichtspalten
an den Verbindungsstellen
von Leuchtenprofilen


Gasket to eliminate light gaps
at connection points
of luminaire profiles.

5. Vor dem Zusammenfügen ist eine
Abdeckdichtung anzubringen.


Apply masking gasket before connecting.



6.




7.



8.

- min/max stripped wire length: 7mm-10mm

- max power supply cable: 1,5mm²




9.

IMPORTANT:


-all sections must be perfectly in line
and if surface isn't even make sure
the elements are horizontally mounted
-if these conditions are not satisfied gaps
will be the result

LIQUID LINE AX | SYSTEM 40MM SURFACE

1. MONTAGE UND INSTALLATION | MOUNTING AND INSTALLATION:



10. Mount the diffuser.
Cut off the silicone diffuser allowance after installation.



11.